



KitchenAid® PRO LINE® Series Toaster 2005 - United States | Canada

Date: January 1, 2005

Name of Product: KitchenAid® ProLine® Toasters

Manufacturer: Whirlpool Corp., of Benton Harbor, Mich

Hazard: An interruption of power to the toaster can cause the heating elements to unexpectedly self-start and could ignite any flammable items left on top of the unit, posing a fire hazard.

Incidents/Injuries: Whirlpool® has received three reports of incidents involving heating elements unexpectedly self-starting, including one case outside the U.S. in which items on top of a toaster caught on fire. There are no reports of personal injury or property damage.

Description:

The recalled KitchenAid® ProLine® countertop toasters are painted die-cast metal or stainless steel and come in 2-slice or 4-slice models. The model and serial numbers, which are on labels affixed to the bottom of the toasters, include:

2 – Slice Models	4 – Slice Models
KPTT780PM KPTT780ER KPTT780BU KPTT780TG	KPTT890PM KPTT890PM KPTT890BU KPTT890TG

Serial Numbers of the recalled products begin with the letters “WTP...” or “WTR...”

Sold At: Various catalogs and specialty retailers nationwide from August 2003 through January 2005 for between \$250 and \$300.

Manufactured In: China

Consumer Contact: Consumers should call KitchenAid® at 1-800-874-0608 between 8 a.m. and 8 p.m. ET Monday through Friday.

Remedy: Consumers should immediately unplug and stop using the toaster and contact KitchenAid® to arrange for a free replacement. Consumers should not return the toaster to the retailer where it was purchased, as retailers are not prepared to take them back.

Representative Models:

